Annexure-I



Figure 2. Stability assessment of existing configuration of slope overlooking km 65.810 of NH44A



Figure 3. Stability of reconfigured slope

Annexure-I

Gabion Basket Drawing



Figure 4. Placement of rock filled gabion baskets

Annexure-I

Chute Drain Drawing

